

[illegible]

Figure 11a

140

70

80

295

50

75

85

8a

200

380

305

390

300

385

368

315

310

320

335

360

350

Defect/Action Information for Quality Ticket: Ticket#: 4895 [SN: M0000001: PN: 130-0466-900: Rev: 001]

Operator: CIENA\dmstestuser1

Process (Test Stage): QT1 - Rx

Symptom Category: 1-N/A

Comment:

Area of Operation: 10G

Process Step (Test): RX grating test

Symptom: N/A

Defect

Action

Action Category: Testing2

Components:

Comment:

Save

Action: Testing2 Step

To get the detailed information on each defect double click on the corresponding row or click on the Feedback button

Status	Defect Category	Defect	Reference Designator(s)
Not Fixed	Component Defects	Damaged	YERE, EEE
No Action	Component Defects	Damaged	tmdd
No Action	Component Defects	Damaged	GGG, DFDD, DDD
No Action	Component Defects	Damaged	

Feedback

Close

7

System Test

CIENA\dmstestuser1

Figure 11b

Figure 12

Figure 12